




АТН-ий үйлчилгээний байр ОУТ-ийн захирал



SGS IMME MONGOLIA LLC

### INSPECTION REPORT


Company : Darkhan Metallurgical Plant

Location: Darkhan Terminal

Date: 2023.9.26

Sample No:	Product weight	H <sub>2</sub> O	Fe	S	Al <sub>2</sub> O <sub>3</sub>	SiO <sub>2</sub>	TiO <sub>2</sub>	P	Number of Car:	
	ton	%	%	%	%	%	%	%		
Lot 98	1	879.30	2.32	60.59	2.82	0.97	4.80	0.10	0.01	10
	2	857.70	1.42	59.68	2.82	1.10	5.45	0.10	0.03	10
	3	860.70	1.82	60.18	2.77	1.05	5.15	0.11	0.03	10
	4	845.30	1.75	59.17	2.65	1.16	5.91	0.12	0.02	7
<b>Average result*</b>		<b>3,443.00</b>	<b>1.83</b>	<b>59.91</b>	<b>2.81</b>	<b>1.07</b>	<b>5.32</b>	<b>0.11</b>	<b>0.02</b>	<b>37</b>

NOTE: \*Average result of all analytes is for summary of product weight.  
 This result format of the inspection sample only for DMP's internal use only.



SGS-IMME Mongolia LLC